UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,864,569 B2 DATED : March 8, 2005

Page 1 of 1

INVENTOR(S) : Paul Evans

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10,

Line 41, "a set or pins" should read as -- a set of pins --.

Line 58, "conductive trucks" should read as -- conductive tracks --.

Line 67, "set or topside circuit components." should read as -- set of topside circuit components. --.

Column 13,

Line 12, "a multiplexer" should read as -- a multiplexor --.

Signed and Sealed this

Twenty-fifth Day of October, 2005

JON W. DUDAS
Director of the United States Patent and Trademark Office